








# CABLING PROCEDURE



CP-400



| TRIM CODE CHART |         |       |       |       |
|-----------------|---------|-------|-------|-------|
| CODE            | A       | B     | C     | D     |
| 401             | 23/64   | 7/32  | .468  | 7/64  |
| 402             | 11/32   | 7/32  | .375  | 3/16  |
| 403             | 7/16    | 7/32  | .493  | 5/32  |
| 405             | 49/64   | 7/32  | .871  | 7/64  |
| 406             | 9/32    | 0     | .093  | 3/16  |
| 407             | 11/16   | 0     | .496  | 3/16  |
| 408             | 45/64   | 7/32  | .809  | 7/64  |
| 409             | 19/64   | 3/16  | .406  | 7/64  |
| 410             | 31/32   | 7/32  | .562  | 5/8   |
| 413             | 21/32   | 7/32  | .717  | 5/32  |
| 414             | 29/64   | 7/32  | .556  | 7/64  |
| 415             | 15/32   | 3/16  | .530  | 5/32  |
| 417             | 41/64   | 7/32  | .743  | 7/64  |
| 418             | 45/64   | 7/32  | .809  | 7/64  |
| 419             | 7/8     | 7/32  | .984  | 7/64  |
| 421             | 15/64   | 0     | .150  | 5/64  |
| 424             | 11/32   | 7/32  | .450  | 7/64  |
| 426             | 17/64   | 7/32  | .406  | 5/64  |
| 430             | 1/2     | 0     | .211  | 1/4   |
| 431             | 9/16    | 0     | .366  | 3/16  |
| 432             | 17/64   | 7/32  | .390  | 3/32  |
| 433             | 5/16    | 7/32  | .375  | 5/32  |
| 435             | 25/64   | 7/32  | .524  | 5/64  |
| 436             | 35/64   | 7/32  | .512  | 1/4   |
| 439             | 7/32    | 7/32  | .345  | 3/32  |
| 440             | 11/32   | 7/32  | .480  | 5/64  |
| 441             | 23/32   | 7/32  | .772  | 5/32  |
| 447             | 1-1/64  | 7/32  | .953  | 9/32  |
| 451             | 1-5/64  | 7/32  | 1.018 | 9/32  |
| 452             | 1-3/32  | 7/32  | .690  | 5/8   |
| 457             | 45/64   | 7/32  | .764  | 5/32  |
| 458             | 5/8     | 7/32  | .671  | 11/64 |
| 459             | 39/64   | 7/32  | .638  | 3/16  |
| 462             | 5/16    | 7/32  | .437  | 3/32  |
| 464             | 15/32   | 7/32  | .493  | 3/16  |
| 465             | 1/4     | 11/32 | .432  | 5/32  |
| 468             | 25/64   | 7/32  | .501  | 3/32  |
| 469             | 1/2     | 7/32  | .580  | 9/64  |
| 470             | 13/32   | 7/32  | .462  | 5/32  |
| 474             | 15/16   | 3/16  | .890  | 15/64 |
| 475             | 1-3/4   | 3/16  | 1.627 | 5/16  |
| 477             | 19/64   | 9/32  | .468  | 7/64  |
| 480             | .281    | .406  | .500  | .187  |
| 484             | 1-13/64 | 7/32  | .948  | 15/64 |
| 487             | 27/64   | 7/32  | .550  | 3/32  |
| 488             | 45/64   | 7/32  | .316  | 39/64 |
| 489             | 11/32   | 11/32 | .500  | 3/16  |
| 493             | 1/4     | 9/32  | .390  | .140  |
| 498             | 23/64   | 7/32  | .316  | 17/64 |
| 5401            | 5/16    | 9/32  | .432  | 5/32  |
| 5402            | 3/8     | 5/16  | .500  | 3/16  |
| 5403            | 5/8     | 5/16  | .750  | 3/16  |
| 5406            | 13/32   | 9/32  | .500  | 3/16  |
| 5407            | 5/16    | 1/4   | .437  | 1/8   |
| 5416            | 3/4     | 0     | .560  | 3/16  |
| 5417            | 19/32   | 1/4   | .703  | 9/64  |
| 5425            | 5/16    | 0     | .187  | 1/8   |
| 5457            | 5/16    | 5/16  | 15/32 | 5/32  |